

## Vehicle Condition Report

Vehicle VIN: 16540184



### Vehicle Information

Year : 1952 Mileage : 96402  
 Brand : Buick Exterior Color : Green  
 Model : Special Trim Color : Beige  
 Series : 50 Trim Type : Cloth  
 Body Type : Sedan  
 Drive Type : Rear Wheel Drive  
 Engine : 4.3L, 8 Cylinder Engine, Gasoline Fuel  
 Transmission : 2-Speed Automatic Transmission

### Inspection Details

Inspection Date : 14 Sep 2012 9:13 AM  
 Inspection ID : 48111  
 Inspector : 3182

Grade : C

**Inspection Notes :** Unable to verify miles due to 5 digit odometer. No plates or insurance, unable to test drive on road. Owner drove approximately 50' to end of driveway and back. Car starts and idles fine after warm up. Slight antifreeze leak noticed after engine was running. L reverse light and brake lights are not working. Clock doesn't work, radio and gauges work. Car was in a museum in TN for 40 years, paperwork photographed. Body has a patina and cracking paint consistent with age of vehicle. Slight rust bottom of Left A Pillar. Wipers inoperable. Engine is a straight 8 cyl 263 cid. Tire size is L78-15, Broadway tires.

### Vehicle Accessories

#### Convenience Exterior

- Chrome Grille

#### Convenience Interior

- Analog Clock

#### Equipment

- Tire/Car Jack & Tools

#### Mechanical

- Battery
- Manual Steering

#### Seating

- Rear Bench Seat

#### Wheels

- Full Size Spare Tire
- Steel Wheels

### Tire Information

	Manufacturer	Size	Depth		Manufacturer	Size	Depth
Left Front :	Other	285/70-15	11/32	Right Front :	Other	285/70-15	10/32
Left Rear :	Other	285/70-15	10/32	Right Rear :	Other	285/70-15	10/32
Spare :	Goodyear	285/70-15	3/32	*Tire Depth of 5/32 or greater is considered normal			

### Vehicle Condition

#### Wear and Tear

Area	Type	Size
1 Front Bumper Cover	Scuffed	Bet 6" - 12"
2 Engine Compartment air intake hoses are torn	Hardware Damage	Bet 6" - 12"
3 Hood Panel	Chipped	Minor
4 Right Front Fender Panel	Chipped	Minor
5 Left Front Fender Panel	Chipped	Minor
6 Roof Panel	Worn	Bet 6" - 12"
7 Left Pillar - Windshield	Other / See Notation	Bet 1" - 3 "



## Vehicle Condition Report

Vehicle VIN: 16540184

slight rust bottom of Left A Pillar		
<b>8</b>	Other / See Notation minor rust drivers floor board	Other / See Notation Bet 1" - 3 "
<b>9</b>	Left Front Seat	Stained Over 12"
<b>10</b>	Left Front Door Panel	Torn Bet 1" - 3 "
<b>11</b>	Rear Seat	Stained Over 12"
<b>12</b>	Rear Seat	Torn Over 12"
<b>13</b>	Left Front Door Panel	Previous Repair Bet 3" - 6"
<b>14</b>	Left Rear Door Panel	Scratched Bet 6" - 12"
<b>15</b>	Left Rear Door Panel	Misaligned Bet 6" - 12"
<b>16</b>	Left Rear Quarter Panel cracked paint	Cracked Over 12"
<b>17</b>	Trunk / Cargo Interior	Chipped Minor
<b>18</b>	Right Front Rocker Panel	Previous Repair Minor
<b>19</b>	Dash Board	Worn Bet 3" - 6"
<b>20</b>	Right Rear Quarter Panel	Scratched Over 12"
<b>21</b>	Other / See Notation Left reverse light not working	Broken Minor
<b>22</b>	Other / See Notation brake lights not working	Broken Minor
<b>23</b>	Other / See Notation antifreeze dripping	Fluid Spillage Minor

## Vehicle Inspection Points

**Legend:** ● Item inspected and is ok    ● Item inspected and contains an issue    ○ Item is not present or could not be inspected

### Engine Compartment

Emission Sticker	○	Check Engine Compartment for Fluid Leaks	●
Hood Struts Operation	○	Battery Is Secure	●
Underhood Insulation	○	Battery Condition	●
Hood Latch Operation	●	Check Transmission For Leaks	●

### Engine Compartment-Parts and Fluid Levels

Windshield Washer Fluid Level	○	Check Power Steering Fluid Level	○
Inspect Hoses	●	Inspect Coolant Levels	●
Check For Engine Oil Sludge	●	Inspector Radiator Hose	●
Check Oil Level	●	Check Transmission Fluid	●
Inspect Belts	●	Check Master Cylinder For Brake Fluid	●

### Exterior-Body Panels

Doors operate properly	●	Inspect Body Panels For Damage	●
Notes: See Vehicle Condition Section			
Tailgate Operation	●	Inspect Roof for Damage	●
Inspect Undercarriage For Damage	●	Frame / Unibody	●
Inspect Truck Bed Condition	○	Check For Rust/ Corrosion	●

Notes: See Inspection Notes Section

Inspect Paint Condition	●	Emblem/ Badge	●
Notes: See Inspection Notes Section			
Inspect Windshield and Other Glass for Damage	●	Inspect Quarter Panels for Damage	●
Inspect Fenders for Damage	●	Door And Side Moldings	●
Trunk Lid Closes Flush With Quarter Panel	●	Inspect Bumpers and Molding For Damage	●

### Exterior-Electronic

Side Markers	○	Side Marker Lights	○
Headlights - Low/ High Beam	●	Tail Lights	●
License Plate Lights And Brackets	●	Reverse Lights	●

Notes: Inoperable / Broken

Fog Lights	○	Brake Lights	●
Notes: Inoperable / Broken			

High Center Third Brake Light	○		
-------------------------------	---	--	--

### Exterior-Hardware

Vehicle Identification Number On Door Jam	●	Vehicle Identification Number On Dashboard	●
Trunk Latch Functions	●	Convertible Top Operational	○
Front Wiper Blades	●	Side Mirrors	●
Notes: Inoperable / Broken			
Remote Gas Cover Latch Operation	○	Gas Cap Condition	●

Door Handles Operational	<input checked="" type="radio"/>	Door Locks And Child Latches Function	<input checked="" type="radio"/>
Rear Window Windshield Wiper Arm	<input type="radio"/>	Antenna Mast Up/ Down	<input checked="" type="radio"/>
Rear Wiper Blades If Applicable	<input type="radio"/>	Side Mirror Extends	<input checked="" type="radio"/>
Chrome Parts	<input checked="" type="radio"/>	Roof Rack	<input type="radio"/>
<b>Interior-Convenience and Power Controls</b>			
Remote Key Fob Functions	<input type="radio"/>	Power Seats	<input type="radio"/>
Alarm	<input type="radio"/>	Power Sunroof	<input type="radio"/>
Rear Window Sunshade	<input type="radio"/>	Window Switches	<input type="radio"/>
Window Operation	<input checked="" type="radio"/>	Power Mirrors	<input type="radio"/>
Manual Door Locks	<input checked="" type="radio"/>	Manual Windows	<input checked="" type="radio"/>
Power Door Locks	<input type="radio"/>	Power Windows	<input type="radio"/>
<b>Interior-Heating and A/C</b>			
Cooled Seat Operation	<input type="radio"/>	Rear Defogger Grid Lines	<input type="radio"/>
Automatic Climate Control	<input type="radio"/>	Recirculating Air Mode	<input type="radio"/>
Heated Seat Operation	<input type="radio"/>	Vent Blower Speed	<input checked="" type="radio"/>
Air Conditioner Blows Cold Air	<input type="radio"/>	Heater Blows Warm Air	<input checked="" type="radio"/>
Fresh Air Mode	<input type="radio"/>		
<b>Interior-Instruments / Controls</b>			
Emergency Road Hazard Lights	<input type="radio"/>	Rear Window Wiper Controls	<input type="radio"/>
Gearshift Operation	<input checked="" type="radio"/>	Horn Functions	<input checked="" type="radio"/>
Check Engine Light	<input type="radio"/>	Sunvisor Vanity Mirrors	<input type="radio"/>
Airbag Warning Light	<input type="radio"/>	Dome Light	<input checked="" type="radio"/>
Odometer Operation	<input checked="" type="radio"/>	Parking Brake	<input checked="" type="radio"/>
Rear View Mirror/ Compass Function	<input type="radio"/>	Sunvisor Lights Function	<input type="radio"/>
Tilt Steering Column Functions	<input type="radio"/>	Warning Lights, Other	<input checked="" type="radio"/>
Knobs, Buttons and Other Controls	<input checked="" type="radio"/>	Dashboard Illumination	<input checked="" type="radio"/>
Defogger Indicator Light	<input type="radio"/>	Dashboard Condition	<input type="radio"/>
		Notes: See Vehicle Condition Section	
Cupholder Extends	<input type="radio"/>	Clock Functions	<input type="radio"/>
		Notes: Inoperable / Broken	
Cigarette Ligher Operational	<input checked="" type="radio"/>	Battery Gauge / Warning Light	<input checked="" type="radio"/>
Hood Release	<input checked="" type="radio"/>	Trunk Release	<input type="radio"/>
ABS Warning Light	<input type="radio"/>	Windshield Wiper Controls	<input type="radio"/>
		Notes: Inoperable / Broken	
<b>Interior-Radio / Entertainment</b>			
Rear Entertainment System and Controls	<input type="radio"/>	Rear Back-up Camera	<input type="radio"/>
Check Radio Controls	<input checked="" type="radio"/>	Speakers	<input checked="" type="radio"/>



## Vehicle Condition Report

Vehicle VIN: 16540184

Navigation System Operation	<input type="radio"/>	CD/DVD	<input type="radio"/>
<b>Interior-Seating and Other Interior</b>			
Cargo Area Carpet	<input type="radio"/>	Airbag - Passenger	<input type="radio"/>
Seating Surfaces - Rear	<input style="background-color: yellow;" type="radio"/>	Carpet - Front	<input type="radio"/>
Notes: See Vehicle Condition Section			
Headliner Condition	<input checked="" type="radio"/>	Smoker Residue Or Odors	<input checked="" type="radio"/>
Tire Jack and Tools	<input checked="" type="radio"/>	Owner's Manual	<input type="radio"/>
Seatbelts - Front	<input type="radio"/>	Seating Surfaces - Front	<input style="background-color: yellow;" type="radio"/>
Notes: See Vehicle Condition Section			
Seat Position Adjusters	<input checked="" type="radio"/>	Spare Tire	<input checked="" type="radio"/>
Trunk Light Operational	<input type="radio"/>	Weather Stripping Condition	<input checked="" type="radio"/>
First Aid Kit If Applicable	<input type="radio"/>	Glove Box	<input checked="" type="radio"/>
Liftgate Struts	<input type="radio"/>	Toolkit Complete	<input checked="" type="radio"/>
Seatbelts - Rear	<input type="radio"/>	Windscreen Functionality, Convertible Top	<input type="radio"/>
Door Sill Plates	<input checked="" type="radio"/>	Interior Trim	<input checked="" type="radio"/>
Tailgate Closing Assist	<input type="radio"/>	Armrest Condition	<input type="radio"/>
Headrests Function Properly	<input type="radio"/>	Airbag - Driver	<input type="radio"/>
Carpet - Rear	<input type="radio"/>		
<b>Test Drive</b>			
Cruise Control Operates	<input type="radio"/>	Steering Wheel Is Centered	<input checked="" type="radio"/>
Steering Wheel Operation	<input checked="" type="radio"/>	Cold/ Hot Starting	<input checked="" type="radio"/>
Engine Idling Normal	<input checked="" type="radio"/>	Engine Operating Temperature	<input checked="" type="radio"/>
Gears Range Operate Smoothly	<input checked="" type="radio"/>	Inspect For Brake Pulsation	<input checked="" type="radio"/>
Inspect For Excessive Smoke	<input checked="" type="radio"/>	Transmission/ Clutch Operation	<input checked="" type="radio"/>
Idle Smoothness	<input checked="" type="radio"/>	Speedometer Functions	<input checked="" type="radio"/>
Acceleration	<input checked="" type="radio"/>	Check For Squeaks	<input checked="" type="radio"/>
Check For Rattles	<input checked="" type="radio"/>	Check For Vibration	<input checked="" type="radio"/>
Excessive Wind Noise	<input checked="" type="radio"/>	Engine Noise	<input checked="" type="radio"/>
Suspension and Handling	<input checked="" type="radio"/>	Vehicle Tracks Straight	<input checked="" type="radio"/>
Starter Functionality	<input checked="" type="radio"/>	Check For Brake Noise	<input checked="" type="radio"/>
Inspect Backup Lights	<input style="background-color: yellow;" type="radio"/>	Check For Unusual Tire Noise	<input checked="" type="radio"/>
Notes: See Vehicle Condition Section			
<b>Tires and Wheels</b>			
Tire Condition and Tread Depth	<input checked="" type="radio"/>	Wheel Condition	<input checked="" type="radio"/>

Date : \_\_\_\_\_ 14 Sep 2012 \_\_\_\_\_      Signature : \_\_\_\_\_


V.4.1

Vehicle Pictures

Picture Description : **Engine**



Picture Description : **Engine**



Picture Description : **Engine**



Picture Description : **Right Side**



Picture Description : **Front**



Picture Description : **Front Corner**



Picture Description : **Roof**



Picture Description : **Tire**



Picture Description : **Tire**



Picture Description : **Tire**



Picture Description : **Tire**



Picture Description : **Interior**






**Vehicle Condition Report**

Vehicle VIN: 16540184

Picture Description : **Key/CD/Manual**




Picture Description : **Left Side**



Picture Description : **Rear Corner**



Picture Description : **Key/CD/Manual**



Picture Description : **Rear**



Picture Description : **Int Cargo**



Vehicle Condition Report

Vehicle VIN: 16540184

Picture Description : **Interior**



Picture Description : **Front**



Picture Description : **Left Side**



Picture Description : **Rear**




Picture Description : **Right Side**



Picture Description : **Vin**



Picture Description : **Odometer**



Damage Pictures

Picture Description : **Other / See Notation Fluid Spillage  
Minor**



Picture Description : **Engine Compartment Hardware Damage  
Bet 6" - 12"**



Picture Description : **Engine Compartment Hardware Damage  
Bet 6" - 12"**

Picture Description : **Hood Panel Chipped Minor**



Picture Description : **Fender Panel Chipped Minor**

Picture Description : **Fender Panel Chipped Minor**



**Vehicle Condition Report**

Vehicle VIN: 16540184

Picture Description : **Roof Panel Worn Bet 6" - 12"**



Picture Description : **Pillar - Windshield Other / See Notation  
Bet 1" - 3"**



Picture Description : **Other / See Notation Other / See  
Notation Bet 1" - 3"**



Picture Description : **Seat Stained Over 12"**



Picture Description : **Seat Stained Over 12"**



Picture Description : **Door Panel Torn Bet 1" - 3"**



Picture Description : **Seat Stained Over 12"**



Picture Description : **Seat Torn Over 12"**



Picture Description : **Door Panel Scratched Bet 6" - 12"**



Picture Description : **Door Panel Misaligned Bet 6" - 12"**



Picture Description : **Quarter Panel Cracked Over 12"**



Picture Description : **Quarter Panel Cracked Over 12"**



